

Castings

John Campbell OBE FREng
Professor of Casting Technology,
University of Birmingham, UK

ELSEVIER
BUTTERWORTH
HEINEMANN

AMSTERDAM • BOSTON • HEIDELBERG • LONDON • NEW YORK • OXFORD
PARIS • SAN DIEGO • SAN FRANCISCO • SINGAPORE • SYDNEY • TOKYO

Contents

Preface vii
Dedication ix
Introduction xi

<i>1. The melt</i>	1
1.1 Reaction of the melt with its environment	2
1.2 Transport of gases in melts	10
1.3 Surface film formation	12
<i>2. Entrainment</i>	17
2.1 Entrainment defect	20
2.2 Entrainment processes	31
2.3 Furling and unfurling	54
2.4 Deactivation of entrained films	61
2.5 Soluble, transient films	63
2.6 Detrainment	64
2.7 Evidence of bifilms	64
2.8 The significance of bifilms	67
<i>3. Flow</i>	70
3.1 Effect of surface films on filling	70
3.2 Effect of entrained films on filling	73
3.3 Fluidity (maximum fluidity length)	74
3.4 Continuous fluidity	95
3.5 Glossary of symbols	98
<i>4. The Mould</i>	99
4.1 Inert mould	99
4.2 Aggregate moulds	100
4.3 Mould atmosphere	105
4.4 Mould surface reaction	111
4.5 Metal surface reactions	114

5. <i>Solidification structure</i>	117
5.1 Heat transfer	117
5.2 Development of Matrix structure	129
5.3 Segregation	139
5.4 Aluminum alloys	147
5.5 Caste irons	156
5.6 Steels	167
6. <i>Gas porosity</i>	178
6.1 Nucleation of gas porosity	178
6.2 Subsurface porosity	186
6.3 Growth of gas porosity	195
6.4 Blowholes	200
7. <i>Solidification shrinkage</i>	205
7.1 General shrinkage behavior	205
7.2 Solidification shrinkage	206
7.3 Feeding criteria	210
7.4 Feeding - the five mechanisms	212
7.5 Initiation of shrinkage porosity	222
7.6 Growth of shrinkage pores	226
7.7 Final forms of shrinkage porosity	227
8. <i>Linear contraction</i>	232
8.1 Uniform contraction	232
8.2 Non-uniform contraction (distortion)	237
8.3 Hot tearing	242
8.4 Cold cracking	258
8.5 Residual stress	259
9. <i>Structure, defects and properties of the finished casting</i>	267
9.1 Grain size	267
9.2 Dendrite arm spacing	270
9.3 Compact defects	275
9.4 Planar defects	279
9.5 Effects of defects on properties at castings	282
9.6 The statistics of failure	301
10. <i>Processing</i>	306
10.1 Impregnation	306
10.2 Hot isostatic pressing	306
10.3 Working (forging, rolling and extrusion)	309
10.4 Machining	399
10.5 Painting	310
11. <i>Environmental interactions</i>	311
11.1 Internal oxidation	311
11.2 Corrosion	313
Postscript	318
References	320
Index	331